

COAST PILOT 3 (Continued)

Page 342—Paragraph 216, line 7 to Paragraph 217, line 1;
read:
be obtained in town.

Chart 12270

Eastern Bay, the approach to Claiborne, St. Michaels, ...
(NOS/03; DOLE/03) 44/03

COAST PILOT 4 35 Ed 2003 Change No. 15
LAST NM 42/03

Page 280—Paragraph 115, line 7; read:
southeastward of Harvey Point. A depth of about 8.8 feet can
be ...
(DB 1553) 44/03

Page 348—Paragraph 80, line 4; read:
21 highway bridge in May 2001; thence in June 2003, 5.4
feet ...
(DB 1789) 44/03

Page 366—Paragraph 88, lines 8 to 9; read:
entrance from seaward without local knowledge. In March
2003, the reported controlling depth was 10.5 feet from ...
(DB 964) 44/03

Page 370—Paragraph 146, lines 6 to 10; read:
an alternate route of the Intracoastal Waterway. In March
2003, the reported midchannel controlling depth in Frederica
River was 6.5 feet.
(DB 964) 44/03

Page 461—Paragraph 132, lines 4 to 6; read:
connect the waterway with Little River Inlet. In August
2003, a reported controlling depth of 8.3 feet was available
with local knowledge to the town of ...
(DB 2231) 44/03

COAST PILOT 7 35 Ed 2003 Change No. 14
LAST NM 42/03

Page 301—Paragraph 164; read:
A **special anchorage** is just S of the breakwater. (See
110.1 and **110.126**, chapter 2, for limits and regulations.) A
seasonal special anchorage and mooring area is just E of
Municipal Wharf No. 2. Mariners operating in the vicinity of
Monterey Harbor are requested to avoid transiting through
this area. Mooring or anchoring is restricted based on current
weather conditions. Permission to moor or anchor may be
obtained through the Office of the Harbormaster.
(CL 1056/03; NOS 18685) 44/03

Page 301—Paragraph 171, line 8; read:
be contacted by phone at 831-646-3950 or by the ...
(CL 1056/03; Internet/03) 44/03